### **XENON HEADLAMPS**

## **NEW FEATURES OF 9.2**

#### **FIVE FAST FACTS**

- Require around 50,000 volts to start.
- Also called HID High Intensity Discharge.

#### The Old Way of Lighting



- Xenon lamps typically have dynamic height adjustment built-in to compensate for the vehicle ride height so they do not dazzle other drivers.
- Xenon lamps produce around 3000 lumens whilst only consuming around 36 watts compared to a traditional headlight which produces around 1500 lumens and consums around 55 watts.

The Xenon Way of Lighting High Voltage Starter Unit



Light Control ECU Dynamic Height Adjuster Unit

 Xenon last three times as long as traditional bulb can cost six times more, and are far more complicated to diagnose in case of problems.

New for 9.2 is the addition of Hyundai This very popular Asian manufacturer has been making substantial in-roads into the European market, with a 127% growth in new car registrations from 2001 - 2005\* In 9.2 we introduce this new manufacturer with the following

- 2002 2006 Model year coverage • 10 Most popular models
- Petrol engines covered Read and clear codes + live data
- ABS Read and clear codes, live data and functional tests \*Figures sourced from SMMT reports.

- Model year coverage extended to 2007 Coverage 1999 - 2007 3 New models added Petrol and Diesel Engines covered on
- NEW Injector programming for 2.ol

Avensis 2003 - 2007

· Systems covered

- Engine - Read and clear codes + live ABS - Read and clear codes + live data

#### Airbag - Read and clear codes Transmission - Read and clear codes **Functional Actuator Tests**

- Model year coverage extended to 2006 - Coverage 1999 – 2006 Diesel engine CRV and FRV Models - 2.2 CTDi N22A1 Diesel CRV and FRV
- 2004 2006 Systems covered on Diesel CRV and FRV models Engine - Read and clear codes + live
- ABS CRV only - Airbags – CRV and FRV

- Coverage extended to include Logan Coverage 2005 – 2007 Engines - Read, clear codes + live
- · Transmission Read, clear codes + live data
- ABS Read, clear codes + live data Airbag - Read, clear codes + live data New Actuator Tests for CAN and Non
- 2000 Model year coverage onwards Fuel Pump Relay

CAN Models

- Reset fuel trims

- Model year coverage extended to 2007 Read and clear codes + live data on 2007 models
- New CAN system diagnostics for Engines - Read and clear codes - ABS - Read and clear codes + live
- Airbags Read and clear codes Transmissions - Read and clea codes + live data
- New Adaptations for Transmis 1994 - 2007 Re-set transmission adaptations
- Expanded DDE6 MAFF adaptation The BMW DDE6 engine managemen is a smart system which can adapt to cope with wear and tear on the engine and its sensors The Mass Air Flow (MAF) sensor is a key component to smooth and economical engine running. - MAF sensors can be considered as

tel +44 (0)1536 413800

email ukscanlines@snapontools.co.uk

web http://diagnostics.snapon.co.uk

Telford Way Industrial Estate, Kettering, Northants NN16 8SN

- When the MAF is replaced with a new unit, the ECU must be informed that a new unit is being fitted. - Failure to do this will lead to poor running and reduced economy

Additional Airbags on E60, E65 & E85

- Codes only

- Model year coverage extended to 2007 - Coverage 1991 – 2007 4 New Models added
- New Model Systems Coverage - Engine - Read and clear codes + live - SRS – Read and clear codes + live
- SLR McLaren - ABS – Read and clear codes + live
- ATM Read and clear codes + live
- **Expanded Systems Coverage** - Airbags – Range Rover 99–01 Read, clear codes + live data - ABS - Range Rover 95-98 - Read, clear codes + live data
- Airbags Discovery II 00-05 Airbags – Freelander 02-05 – Read, clear codes + live data

#### PSA Citroen - Peugeot Model year coverage extended to 2007

- Coverage 1995 2007 5 New Models – 1/4 Engine Combination Systems Covered on New Models
- Engines Read, clear codes + live data - ABS - Read, clear codes and live data Functional tests
- ABS Electro Valves and pump motor • Engine – Injector, Fan Control, EGR, Check for spark
- SIR where applicable BSI (Body Systems Interface) Expanded - 407 Models covered 2004 - 2007 CAN gateway to ancillary systems
- warning indicator - ABS Mk 60.0 added for 207. New National version factor Look C3 and 1007 Restyle models - C Class 204 body code 2007 mode New TPMS (Tyre Pressure Monitoring System) added Read service data and clear service
- C6 Models Read, clear codes + live - Reset mistaken service - If performed

#### - E Class 210 body code 2000 - 2003 Model year coverage extended to 2007 model year Newer type Kombi Instruments - Coverage 1992 – 2007

- Codes, data and special functions on 2007 models as below New Model added New Xenon Light Module
- Reprogram Xenon Light Modules and realign headlamps on some models Mondeo 2001 – 2007 Codes – Data and module reprogramming - Focus 2005 – 2007 Codes – Data and module reprogramming - Galaxy 2006 – 2007 Codes and data - S-Max 2006 – 2007 Codes and data

#### VAG - VW - Audi - SEAT - Skoda

- · Brake Bleed Procedure Added Mk60/70, Mk25 ESP25 - This procedure is an essential service function, and is also required when replacing the ABS pump or changing brake fluid.
- Models covered 2005 2007 Long Coding Comfort System This new and important feature configuration of the conveni module on the Passat 3C chassis i.e. modify door locking configuration, selective door locking, Flashing
- indicators on locking/unlocking etc. Long Coding CAN Gateway

- New ABS Pump and Solenoid - Another new and important feature enables the technician to add **Functional Tests for** Corsa C, Astra G, Zafira B, Meriva or modify systems on the CAN eway, i.e. add a trailer module and Tigra B models
- Xenon lights etc. • 9 New Engines Added for Corsa D, Astra H and Vectra C Models New Data Lists for 9.2 Z14XEL, Z16LET, Z16XE1, Z16XER, Over 20 new Engine data lists added

- Model year coverage extended to 2007 • 2 New Models Systems Coverage New Models
- Engines, ATM, ABS, SRS, nstruments - Read and clear codes
- + live data SIR – Diagnostics service reset
- Engines, ATM, ABS, SRS, Steering column module, Passenger contro module, Upper control module - Read and clear codes + live data

- C Class 204 body 2007 onwards

- E Class 210 body 2000 - 2003

Expanded Adaptation Capabilities

Reset Throttle Valve Actuator

Reset Transmission Shift Values

Expanded Diagnostic SIR Capabilitie

Program and configure service

Read service data and clear service

- Read service data and clear service

Xenon light – Bi-Xenon Light

1 Model year onwards

Read, clear codes + live data

Perform special functions, like

Model year coverage extended to

- Engines Z2oDM, Z2oDMH and

- Systems Covered on Antara

- Engines - Read, clear codes + live

- ATM - Read, clear codes + live data

- ABS - Read, clear codes + live data

- Airbags - Read and clear codes +

Expanded CIM Module Capabilities

- Vectra C - CIM (steering column

module) unit reconfigure and

remote key programming.

live data

bulb removal procedure and curve

illumination tests and tourist mode

New instrument panel – Read, clear

codes + live data and actuator tests

- ATM - Read and clear codes + live data

codes + live data

- Reset Crank Sensor

- EGS 52 ATM

indicator

indicator

- SVS lamp - Control module rear, Power supply unit, TPM - Read and clear codes - Boost pressure valve Expanded Systems Coverage Glow time relay - S Class 221 body 2006 onwards Throttle solenoid valve
- New instrument panel Read, clear Fuel leakage codes + live data and actuator tests Turbo bypass solenoid New instrument panel - Read, clear Loop status Secondary air pump relay
  - Special functions include Electronic throttle contro Program idle speed Reset O2 block learn man
  - Reset learned values Diesel Injector programming Replace Mass Air Flow Senso - Replace Rail Pressure Sensor - Replace Pre-Catalyst

Z1DTR, Z16LER, Z28NEL, Z28NET and

All new Engines – Read, clear codes

Z<sub>2</sub>8HEH

+ live data

· Actuator tests include

- Fuel pump relay

- EGR Solenoid - FGR cooler bypass solenoid

Fuel tank vent valve

Cooling fan speed

Port deactivation

Intake manifold valve - Malfunction Indicator Lamp (MIL)

#### AFL - Alfa - FIAT - Lancia Model year coverage to 2007

Compression test

- Coverage 1995 2007 Read, clear codes and live data Functional tests
- New Fiat 500 Model Added - Engine - Read, clear codes + live - ABS – Read, clear codes + live data Airbag – Read, clear codes + live
- Injector coding
- New Engines - 1.9 Diesel – EDC16CC39 – Alfa 147 - 2.2 Petrol - MED 7.6.1 - Alfa 159
- Expanded Injector Coding Capabilities - Injector coding added for 2.45 cylinder AFL engine – EDC16C39 Alfa 159 - Croma Restyle
- · New and updated ABS systems for Bosch ABS 8 system Bosch 8 ASR ABS

- Bosch 8 VDC ABS up to 2007

- Model year coverage to 2007 New Engines and Airbag systems - Kubistar – 1.5 Diesel
- Interstar Airbags added Primastar - Airbags added and Injector coding on 2.0 M9R engine New Tiida Model added - Petrol engine - Read, clear codes +
- live data - ABS – Read and clear codes - Airbags – Read and clear codes
- Disable injectors Vary ignition timing
- Cooling fan
- replace including transponder and ABS moto ABS solenoid valves
  - Snap-on.

THE THINKING IS IN YOUR HANDS.

....

VERUS

SUPPORT SEMINARS FINANCE SUPPORT SEMINARS BINAMES PRODUCTS TRAINING SOFTWARE SUPPORT SEMINARS FINANCE PRODUCTS TRAINING SOFTWARE SUPPORT SEMINARS FINANCE PRODUCTS SOLUSPRO **ETHOS** 



THE THINKING IS IN YOUR HANDS.

**WHAT'S NEW** 

MODIS

9.2 Vehicle Application Software

# 9.2 VEHICLE COMMUNICATIONS SOFTWARE - IT MEANS BUSINESS

# JOB CARD

MAKE Vauxhall FUEL Diesel

MODEL Vectra C YEAR 2004

### INSTRUMENT PANEL PROBLEM DETAILS

Whilst driving the vehicle the instrument cluster lights up like a Christmas tree, all of the gauges including the speedo and the rev counter drop to zero. After the vehicle is turned off with the key, the instrument panel remains illuminated.

### DIAGNOSIS

With 9.2 software, the CIM and the instrument cluster are interrogated. Multiple fault codes are present in the CIM. A screen capture is made of the codes using the S button and saved to a USB stick drive. The codes are cleared, but CIM fault codes remain. A meter is used to check the CAN wiring between the affected modules, all O.K. The live data also checks out O.K on the instrument cluster.

### SOLUTION

A replacement CIM unit is ordered from the main dealer, and then fitted and more importantly coded to suit the configuration of the vehicle using 9.2 software. Problem solved job completed.

### SO WHAT'S NEW IN 9.2?

- Hyundai has been added covering the 10 most popular models.
- 18 major vehicle manufacturer software titles are updated and enhanced with model year coverage extended to 2007.
- Over 2,100 new vehicle selections have been added.
- Plus 5,300 new and extra data PID's (Parameter
- Trouble codes and descriptions give the technician a guide to tracing the route cause of the problem, ther 23,000 have been introduced xstensive 172,000.

Software and information development remains at the heart of our business, because we believe that it's essential to yours. Our focus on delivering accurate information, linked to fast vehicle communications software with built in functionality enables our customers to deal with the fundamental diagnostic tasks faced every day on modern vehicles. In addition to this, we are dedicated to supporting our Customers with effective product support, user training plus informative and

knowledge building TechEd ser

# JOB CARD

MAKE Hyundai FUEL Diesel

MODEL Santa Fe 2.0 TD **YEAR** 2003

9.2

(9.2

9.2 equipped

(9.<sub>2</sub>

9.2

#### **BRAKE SYSTEM** PROBLEM DETAILS

Brake system problem. When the customer slows to a stop the

### **DIAGNOSIS**

With 9.2 software the technician assesses the vehicles fault codes, but none are stored. Looking through the live data in graphing mode whilst driving the vehicle the technician notices that the off side front wheel speed data value has dropped to zero, whilst the other three wheel speeds are registering 11mph.

### SOLUTION

The technician uses a multimeter to check the sensor output and wiring which checks out fine. Disconnecting the sensor with the ignition on flagged a fault code. A replacement sensor is fitted. 9.2 software clears the code no problem. A roadtest proves that the job has been successfully completed.

# JOB CARD

MAKE Ford FUEL Petrol

9.2

9.2

MODEL Mondeo ST220

YEAR

9.2

9.2 equipped

9.2

9.2

9.2

FAILED XENON UNIT PROBLEM DETAILS Whilst driving at night the customer receives a dash board

notification of a failed headlamp bulb.

# DIAGNOSIS

This vehicle is fitted with Xenon headlamps. The Near side lamp is inoperative. With 9.2 software our technician assesses the Xenon headlamp unit for fault codes and retrieves a diagnostic trouble code for a failed Xenon unit. There is a special procedure to replace this unit, and also to set the unit

#### SOLUTION

In order to fit a new headlamp unit, the system has to be set into a special mode and a specific llowed. This is because the system uses around 40,000 volts to start the Xenon bulb, and the system sets the direction of the light beam relative to the ride height of the vehicle. 9.2 software allows the technician to safely replace the unit and to ensure that it is correctly reinitialised and



MAKE Mercedes FUEL Petrol

MODEL SLK 350 Auto YEAR 2002

(9.<sub>2</sub>

9.2

(9.<sub>2</sub>

9.2 equipped

### GEAR SHIFT MODULE PROBLEM DETAILS

When driving the vehicle in full auto mode it 'jumps' gears. When driving the vehicle in manual mode, moving up through the gears using the stick, the gearbox changes O.K. The vehicle is also O.K. when driven in W (winter mode). The vehicle owner had been quoted £1200 for a gearbox refurbishment.

## DIAGNOSIS

Using 9.2 Mercedes application the technician reviewed fault codes and the live data stream for the EGS (Electronic Gear System). As the shift lever was moved through the gear selection range the data parameter for currently selected gear read F (rather than the gear number) when in gear pos and 2. The wiring was checked on the gear shift module, which

### SOLUTION

A new gear shift module was fitted. The adaptation values for the shift module, which are stored by the EGS, were reset by the 9.2 software. The vehicle was road tested and the problem

# **JOB CARD**

MAKE Volkswagen FUEL Diesel

MODEL Passat YEAR 2006

### ABS SYSTEM PROBLEM DETAILS

ABS Warning Lamp Illuminated permanently. No ABS system function. No codes or data available.

## DIAGNOSIS

The ABS control unit was checked for powers and earths, all were present. The ABS unit has failed internally. A replacement ABS unit was sourced and fitted to the vehicle. When the key is turned on the ABS performs a self test and the warning lamp goes out. The ABS unit requires the air, which was trapped inside during the change procedure, to be bled from the brake system before the car can be driven.

### SOLUTION

Using 9.2 software, the technician can select the Bleed ABS function from the Volkswagen menu. 9.2 Se to the ABS ECU for it to enter the factory bleed mode. This causes the hydraulic system to pressurise and enables the technician to bleed the brakes to rid them of the air trapped inside. Previously, this job would have to have been sent to the dealer. 9.2 enables the independent workshop to complete the job.



9.2

9.2



THE THINKING IS IN YOUR HANDS.



THE THINKING IS IN YOUR HANDS



